

SGS MUSCOWPETUNG

ABORIGINAL CONSTRUCTION MONITORING

WEEKLY REPORT

SPREAD # 3

NOVEMBER 20TH TO NOVEMBER 26TH, 2017



Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	0			
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	0			

Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	0			
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	0			
Trees (Red Willow)	0			
Wetlands	0			
Watercourse Crossing	1	South Saskatchewan River Crossing. Horizontal directional drilling and testing the water turbidity.	South Saskatchewan Crossing ongoing.	Ongoing

ISO 9001: 2008 Registered OHSAS 18001:2007 Registered



Additional Observations and Summary of Activities or Concerns

The horizontal directional drilling at the South Saskatchewan River is still ongoing. They have reached 891 metres with the 36-inch reamer early in the week. They had to trip back all week to clean out the bore hole. Now they have tripped back in and drilling two days ago and were at 1000 metres with the 36-inch reamer. They have reached the east bank of the river and have started doing frack walks. There are no concerns currently. They should be reaching the exit point within the next few days and they will be closely monitoring for any fracks.

Currently the testing of the water turbidity by Golder Associates is ongoing and has remained consistent throughout the week. It is closely being monitored as they are underneath the river now. Testing of the turbidity is performed every two hours throughout the day and there is constant communication between the Golder Associates and the drilling team.

At present, there are quite a few tie ins that need to be done. This week my co-workers and I have observed tie ins and the process of the backfill of the tie ins. There has been bores that have been done this week underneath road crossings. There are no concerns currently.

Hydro testing of the mainline is still ongoing. They have filled the mainline with water and tested the first phase of the line. The second phase of the testing of the mainline has been completed and the third phase is near completion. When that is done they will be pushing the water back to where they first tested and drain the water onto a field.

.



Photos of Sites Visited & Topics Discussed This Week

East Elevation

② 276°W (T) ⑤ 51°20'43"N, 106°56'50"W ±16.4ft ▲ 1805ft



CREW WORKING ON HOARDING THE PIPE



South East Elevation

© 317°NW (T) ● 51°9'45"N, 106°29'35"W ±16.4ft ▲ 1974ft



BACKFILLING AND PACKING SOIL ON HOTLINES



East Elevation



VISUAL OBSERVATION DURING FRACK WALK



East Elevation



GOLDER ASSOCIATES GOING OUT ON WATER TO OBTAIN WATER SAMPLES



North West Elevation 22 Nov 2017, 10:

CORRISION TESTING ON PIPE THAT WAS PULLED FROM UNDERNEATH A ROAD



South Elevation


@ 348°N (T) ● 51°4'53"N, 106°17'45"W ±16.4ft ▲ 1886ft



SAND BLASTING A TIE IN



West Elevation



EXIT POINT OF HORIZONTAL DIRECTIONAL DRILLING



South Elevation

② 22°N (T) ● 51°11'50"N, 106°35'13"W ±16.4ft ▲ 1992ft



HOE PACKING OF BACKIFF SOIL



South East Elevation



CREW WORKING ON A TIE IN



South East Elevation



HEATIN GUP BEFORE A TIE IN



Approvals

Prepared by

m	
_	
Gary Gopher	
Senior Construction Monitor	November 25, 2017
Deviewed by	
Reviewed by	
J Rock	
Joseph Roach	
Project Manager	November 27, 2017
Approved by	
III.	

SGS Canada Inc.

Emmanuel Olotu, P.Eng.

Technical Manager, Geotechnical

#1450 - 407 2nd Street SW (14th Floor) , Calgary Alberta T2P2Y3 **t**: (403) 278-9730

ISO 9001: 2008 Registered OHSAS 18001:2007 Registered

November 27, 2017