

LDAR Report

Enbridge

Accident Storage Compressor Station

Quarterly Report COMAR 26.11.41 PERIOD: Q2 2022

Prepared By:

Montrose Air Quality Services, LLC

412 Darby Way (Suite 2)

Bridgeville, Pennsylvania 15017

www.montrose-env.com

Report Generated on: 7/29/2022



| Company: | Enbridge | | Report: | Quarterly LDAR | | | | |
|--|--|---------------------------------|-----------------------|-----------------------------|-------------------------|--------------|--|--|
| District: | Storage-North | | Regulation(s): | COMAR 26.11.41 | | | | |
| Facility Name: | Accident Storage Compressor Station | | Report Date: | 2022-Jul-29 | | | | |
| | | | Period: | 2022-Apr-01 | TO | 2022-Jun-30 | | |
| This report satisf | This report satisfies the requirements of COMAR 26.11.41 for the collection of fugitive emissions components at the above referenced compressor station. | | | | | | | |
| | Information required to be reported per §26.11.41 07 A.(1)(a) | | | | | | | |
| Monitorin | Monitoring Quarter | | N/A | N/A | N/A | N/A | | |
| Survey Star | Survey Start Date/Time | | | | | | | |
| Survey End Date/Time | | 06/29/2022 12:00 PM | | | | | | |
| | LDAR Instrument | | | | | | | |
| | §26.11.41 07 A.(1)(a)(iii) Deviations from Monitoring Plan | | | | | | | |
| Deviation(s) | Deviation(s) Explanation | | | | | | | |
| | §26.11.41 07 A.(1)(a)(iv) - Number and type of components for which fugitive emissions were detected | | | | | | | |
| Val | * * | 3 | | | | | | |
| | Connectors | | | | | | | |
| | elief Devices | | | | | | | |
| · | ded Lines | | | | | | | |
| Flanges | | 5 | | | | | | |
| • | Compressors | | | | | | | |
| | Instruments | | | | | | | |
| | Meters Other | | | | | | | |
| | | 17 | | | | | | |
| Total No. of L | Total No. of Leaks Detected | | | | | | | |
| | | and type of components | that were tagged as a | result of not being repa | aired during the monito | oring survey | | |
| Val | | 3 | | | | | | |
| | ectors | 9 | | | | | | |
| Pressure Re | | | | | | | | |
| | Open-Ended Lines | | | | | | | |
| | nges | 5 | | | | | | |
| Compr | | | | | | | | |
| Instru | | | | | | | | |
| | ters | | | | | | | |
| Ott | Other | | | | | | | |
| | §26.11.41 07 A.(1)(a)(v) - Number and type of difficult-to-monitor and unsafe-to-monitor fugitive emission components monitored | | | | | | | |
| | ves | | | 1 | | 1 | | |
| Connectors | | | | 1 | | | | |
| Pressure Relief Devices Open-Ended Lines | | | | 1 | | | | |
| · | | | | 1 | | | | |
| Flanges | | | | | | | | |
| Compressors | | | | | | | | |
| Instruments Meters | | | | - | | | | |
| | | | | - | | | | |
| Other | | 11 07 A (1)(a)(iv) Data of succ | 61 61 6 11 | mission sommonout (soo Bono | | | | |

§26.11.41 07 A.(1)(a)(ix) - Date of successful repair of the fugitive emission component (see Repair List).

§26.11.41 07 A.(1)(a)(viii) - Number and type of fugitive emission components placed on delay of repair and explanation for each delay of repair (see DOR List).

§26.11.41 07 A.(1)(a)(x) - Type of instrument used to resurvey a repaired fugitive emissions component that could not be repaired during the initial fugitive emissions finding (see Repair List).



Fugitive Emissions Components Placed on DOR

This summary satisfies the annual reporting requirements of §26.11.41 07 A.(1)(a)(viii), "number and type of fugitive emission components placed on delay of repair and explanation for each delay of repair".

| Component | | | | | | |
|----------------------------------|------------------|-------------------|--------------------------|-------------------|------------------------------|--|
| Quarter | Q2 | N/A | N/A | N/A | N/A | |
| Survey Date | 6/29/2022 | | | | | |
| Valves | 2 | | | | | |
| Connectors | 3 | | | | | |
| Pressure Relief Devices | | | | | | |
| Open-Ended Lines | | | | | | |
| Flanges | 5 | | | | | |
| Compressors | | | | | | |
| Instruments | | | | | | |
| Meters | | | | | | |
| Other | | | | | | |
| Total No. of Leaks placed on DOR | 10 | | | | | |
| Date Surveyed | Emission ID # | Component Type | Current Repair Status | _ | of Repair / Justification | |
| 06/29/2022 | 34825300 | Flange | Delay of Repair | Shutdown required | | |
| 06/29/2022 | 34825302 | Flange | Delay of Repair | Shutdown required | | |
| 06/29/2022 | 34825306 | Flange | Delay of Repair | Shutdow | n required | |
| 06/29/2022 | 34825307 | Connector | Delay of Repair | Shutdow | n required | |
| 06/29/2022 | 34825308 | Flange | Delay of Repair | Shutdow | n required | |
| 06/29/2022 | 34825309 | Connector | Delay of Repair | Shutdow | n required | |



Fugitive Emissions Components Repaired During Reporting Period

This summary satisfies the annual reporting requirements of §26.11.41 07 A.(1)(a)(ix), "date of successful repair of the fugitive emission component" and §26.11.41 07 A.(1)(a)(x), "type of instrument used to resurvey a repaired fugitive emissions component that could not be repaired during the initial fugitive emissions finding".

| Date Surveyed | Emission ID # | Date of Successful Repair | Repair Confirmation Method / Instrument |
|---------------|---------------|------------------------------|--|
| 06/29/2022 | 34825299 | 07/11/2022 | Bubble Test |
| 06/29/2022 | 34825301 | 07/05/2022 | Bubble Test |
| 06/29/2022 | 34825303 | 07/05/2022 | Bubble Test |
| 06/29/2022 | 34825304 | 07/05/2022 | Bubble Test |
| 06/29/2022 | 34825305 | 07/05/2022 | Bubble Test |
| 06/29/2022 | 34825312 | 07/04/2022 | Bubble Test |
| 06/29/2022 | 34825315 | 07/04/2022 | Bubble Test |