



## LDAR Report

# Enbridge

## Accident Storage Compressor Station

### Quarterly Report

COMAR 26.11.41

PERIOD: Q4 2022

Prepared By:

**Montrose Air Quality Services, LLC**

412 Darby Way (Suite 2)

Bridgeville, Pennsylvania 15017

[www.montrose-env.com](http://www.montrose-env.com)

Report Generated on: 1/12/2023

<b>Company:</b>	Enbridge	<b>Report:</b>	Quarterly LDAR		
<b>District:</b>	Storage-North	<b>Regulation(s):</b>	COMAR 26.11.41		
<b>Facility Name:</b>	Accident Storage Compressor Station	<b>Report Date:</b>	2023-Jan-12		
<b>GPS Coord.:</b>		<b>Period:</b>	2022-Oct-01	TO	2022-Dec-31

This report satisfies the requirements of COMAR 26.11.41 for the collection of fugitive emissions components at the above referenced compressor station.

**Information required to be reported per §26.11.41 07 A.(1)(a)**

Monitoring Quarter	Q4	N/A	N/A	N/A	N/A
Survey Start Date/Time	11/14/2022 8:30 AM				
Survey End Date/Time	11/14/2022 14:30:00 PM				
LDAR Instrument	Optical Gas Imaging/GFX-320				
§26.11.41 07 A.(1)(a)(iii) Deviations from Monitoring Plan	No deviations from the Monitoring Plan				
Deviation(s) Explanation	N/A				

**§26.11.41 07 A.(1)(a)(iv) - Number and type of components for which fugitive emissions were detected**

Valves	10				
Connectors	5				
Pressure Relief Devices					
Open-Ended Lines					
Flanges					
Compressors					
Instruments					
Meters					
Other					
<b>Total No. of Leaks Detected</b>	<b>15</b>				

**§26.11.41 07 A.(1)(a)(vii) – Number and type of components that were tagged as a result of not being repaired during the monitoring survey**

Valves	3				
Connectors	1				
Pressure Relief Devices					
Open-Ended Lines					
Flanges					
Compressors					
Instruments					
Meters					
Other					

**§26.11.41 07 A.(1)(a)(v) - Number and type of difficult-to-monitor and unsafe-to-monitor fugitive emission components monitored**

Valves					
Connectors					
Pressure Relief Devices					
Open-Ended Lines					
Flanges					
Compressors					
Instruments					
Meters					
Other					

§26.11.41 07 A.(1)(a)(ix) - Date of successful repair of the fugitive emission component (see Repair List).

§26.11.41 07 A.(1)(a)(viii) - Number and type of fugitive emission components placed on delay of repair and explanation for each delay of repair (see DOR List).

§26.11.41 07 A.(1)(a)(x) - Type of instrument used to resurvey a repaired fugitive emissions component that could not be repaired during the initial fugitive emissions finding (see Repair List).



Fugitive Emissions Components Placed on DOR					
This summary satisfies the annual reporting requirements of §26.11.41 07 A.(1)(a)(viii), "number and type of fugitive emission components placed on delay of repair and explanation for each delay of repair".					
Component					
Quarter	Q4	N/A	N/A	N/A	N/A
Survey Date	11/14/2022				
Valves	2				
Connectors	1				
Pressure Relief Devices					
Open-Ended Lines					
Flanges					
Compressors					
Instruments					
Meters					
Other					
Total No. of Leaks placed on DOR	3				
Date Surveyed	Emission ID #	Component Type	Current Repair Status	Delay of Repair Explanation / Justification	
03/14/2022	88110071	Connector	Delay of Repair	Shutdown required	
11/14/2022	92510155	Connector	Delay of Repair	Shutdown required	
11/14/2022	92510159	Valve	Delay of Repair	Shutdown required	
11/14/2022	92510160	Valve	Delay of Repair	Shutdown required	

**Fugitive Emissions Components Repaired During Reporting Period**

This summary satisfies the annual reporting requirements of §26.11.41 07 A.(1)(a)(ix), "date of successful repair of the fugitive emission component" and §26.11.41 07 A.(1)(a)(x), "type of instrument used to resurvey a repaired fugitive emissions component that could not be repaired during the initial fugitive emissions finding".

Date Surveyed	Emission ID #	Date of Successful Repair	Repair Confirmation Method / Instrument
06/29/2022	34825300	10/19/2022	Bubble Test
06/29/2022	34825302	10/19/2022	Bubble Test
06/29/2022	34825306	10/19/2022	Bubble Test
06/29/2022	34825307	10/19/2022	Bubble Test
06/29/2022	34825308	10/19/2022	Bubble Test
06/29/2022	34825309	10/19/2022	Bubble Test
06/29/2022	34825310	10/19/2022	Bubble Test
06/29/2022	34825311	10/19/2022	Bubble Test
06/29/2022	34825313	11/14/2022	OGI
06/29/2022	34825314	11/14/2022	OGI
08/29/2022	40825214	11/14/2022	OGI
08/29/2022	40825215	11/14/2022	OGI
08/29/2022	40825220	11/14/2022	OGI
08/29/2022	40825230	10/19/2022	Bubble Test
08/29/2022	40825231	10/19/2022	Bubble Test
04/07/2021	51810018	10/24/2022	Bubble Test
04/07/2021	51810020	10/24/2022	Bubble Test
11/14/2022	92510151	11/16/2022	OGI
11/14/2022	92510152	11/16/2022	OGI
11/14/2022	92510153	11/16/2022	OGI
11/14/2022	92510154	11/16/2022	OGI
11/14/2022	92510156	11/17/2022	OGI
11/14/2022	92510157	11/16/2022	OGI
11/14/2022	92510158	11/16/2022	OGI
11/14/2022	92510161	11/16/2022	OGI
11/14/2022	92510162	11/16/2022	OGI
11/14/2022	92510163	11/16/2022	OGI
11/14/2022	92510164	11/29/2022	Bubble Test
11/14/2022	92510165	11/17/2022	OGI