

### **LDAR Report**

# **Enbridge**

## **Accident Storage Field**

Quarterly Report COMAR 26.11.41 PERIOD: Q1 2022

Prepared By:

Montrose Air Quality Services, LLC

412 Darby Way (Suite 2)

Bridgeville, Pennsylvania 15017

www.montrose-env.com

Report Generated on: 5/4/2023



Company:	Enbridge	Report:		Quarterly LDAR	
District:	Storage-North	Regulation(s):		COMAR 26.11.41	
Facility Name:	Accident Storage Field	Report Date:	2023-May-04		
		Period:	2023-Jan-01	TO	2023-Mar-31

This report satisfies the requirements of COMAR 26.11.41 for the collection of fugitive emissions components at the above referenced compressor station.

	Information required to	pe reported per	1926.11.41 U/ A.(1)(	a)	
Monitoring Quarter	Q1	N/A	N/A	N/A	N/A
Survey Start Date/Time	03/07/2023 7:15 AM				
Survey End Date/Time	Mar 9, 2023 2:15 PM				
LDAR Instrument	Optical Gas Imaging/GFX- 320				
26.11.41 07 A.(1)(a)(iii) Deviations from Monitoring Plan	No deviations from the Monitoring Plan				
Deviation(s) Explanation	N/A				
§26.11.41 07 A.(1	)(a)(iv) - Number and type o	of components for	r which fugitive emissi	ons were detected	
Valves	6				
Connectors	3				
Pressure Relief Devices					
Open-Ended Lines					
Flanges					
Compressors					
Instruments					
Meters					
Other					
Total No. of Leaks Detected	9				
§26.11.41 07 A.(1)(a)(vii) - Number	and type of components tha	at were tagged as	a result of not being re	epaired during the monit	oring survey
Valves	3				
Connectors	2				
Pressure Relief Devices					
Open-Ended Lines					
Flanges					
Compressors					
Instruments					
Meters					
Other					
§26.11.41 07 A.(1)(a)(v) - Numl	ber and type of difficult-to-n	nonitor and unsaf	e-to-monitor fugitive e	mission components mo	nitored
Valves					
Connectors			1	Τ'	T -
Connectors Pressure Relief Devices					
Pressure Relief Devices					
Pressure Relief Devices Open-Ended Lines					
Pressure Relief Devices Open-Ended Lines Flanges					
Pressure Relief Devices Open-Ended Lines Flanges Compressors					

§26.11.41 07 A.(1)(a)(ix) - Date of successful repair of the fugitive emission component (see Repair List).

§26.11.41 07 A.(1)(a)(viii) - Number and type of fugitive emission components placed on delay of repair and explanation for each delay of repair (see DOR List).



#### **Fugitive Emissions Components Placed on DOR**

This summary satisfies the annual reporting requirements of §26.11.41 07 A.(1)(a)(viii), "number and type of fugitive emission components placed on delay of repair and explanation for each delay of repair".

Component					
Quarter	Q1	N/A	N/A	N/A	N/A
Survey Date	3/7/2023				
Valves					
Connectors	1				
Pressure Relief Devices					
Open-Ended Lines					
Flanges					
Compressors					
Instruments					
Meters					
Other					
Total No. of Leaks on DOR	0				
Date Surveyed	Emission ID #	Component Type	Current Repair Status	Delay of Repair Explanation / Justification	
03/08/2023	32625519	Connector	Delay of Repair	Shutdow	n required



#### **Fugitive Emissions Components Repaired During Reporting Period**

This summary satisfies the annual reporting requirements of §26.11.41 07 A.(1)(a)(ix), "date of successful repair of the fugitive emission component" and §26.11.41 07 A.(1)(a)(x), "type of instrument used to resurvey a repaired fugitive emissions component that could not be repaired during the initial fugitive emissions finding".

Date Surveyed	Emission ID #	Date of Successful Repair	Repair Confirmation Method / Instrument	
03/07/2023	32625546	3/7/2023	OGI	
03/07/2023	32625547	3/7/2023	OGI	
03/07/2023	32625548	3/9/2023	Bubble Test	
03/07/2023	32625549	3/7/2023	OGI	
03/07/2023	32625550	3/7/2023	OGI	
03/08/2023	32625552	3/8/2023	OGI	
03/08/2023	32625553	3/8/2023	OGI	
03/08/2023	32625554	3/8/2023	OGI	

Report Generated on: 5/4/2023