

### **SGS MUSCOWPETUNG**

### **ABORIGINAL CONSTRUCTION MONITORING**

**WEEKLY REPORT** 

SPREAD # 3

FEBURARY 5<sup>TH</sup> TO FEBURARY 11<sup>TH</sup>, 2018



#### **Social and Cultural Features**

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	0			
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	0			

#### **Environmental Features**

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	0			
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	0			
Trees (Red Willow)	0			
Wetlands	0			
Watercourse Crossing	0			



#### **Additional Observations and Summary of Activities or Concerns**

The bore at the river was cleaned and dried early in the week. There were nine tie ins on both sides of the river and they were completed by Friday. As of yesterday, they were near completion of backfilling all tie ins of exit point of the river. On the West side of the river they wrapped rock shield around the pipe where it was needed at the entry point of the East side of the river.

They have finished compacting sand at valve eight and they have constructed hoarding around it yesterday. They will be torqueing the valve to specifications. Also, they did the same thing backfilling and hoarding valve number seven.

Also, they have opened top soil to create an alley way for the farmers cows this spring.

The deficiency crew have been working on the deficiencies on the right of way and will continue into next week.

There have been no environmental issues up to date. Completion of spread three is near the end.



### **Photos of Sites Visited & Topics Discussed This Week**


## **North East Elevation**



CUTTING TEST HEAD OFF AT EXIT POINT



## **East Elevation**



TIE IN




# **North West Elevation**



BACKFILLING VALVE NUMBER SEVEN



# **South West Elevation**



deficiency crew PICKING UP SKIDS

SGS Canada Inc.

#1450 - 407 2<sup>nd</sup> Street SW (14<sup>th</sup> Floor), Calgary Alberta T2P2Y3 t: (403) 278-9730

ISO 9001: 2008 Registered OHSAS 18001:2007 Registered



## **West Elevation**



**HOARDING** 



# **South West Elevation**



**INSTALLING PIGS AT TEST HEAD** 



# North Elevation



PICKING UP RIGS MATS



# **North West Elevation**



CUTTING OFF SECTION OF THE BORE

www. sgs.com



# **West Elevation**



BACKFILLING VALVE

www. sgs.com



# **South East Elevation**

© 335°NW (T) ● 51°20'56"N, 106°58'0"W ±16.4ft ▲ 1753ft



SPACING A TIE IN





**ROCK SHIELD** 



# **East Elevation**



**BACKFILLING DITCH LINE** 



# **North West Elevation**



**BACKFILLING ENTRY POINT** 



### **Approvals**

### **Prepared by**

/mm	
Gary Gopher	
Senior Construction Monitor	February 11, 2018
Reviewed by	
J Rock	
Joseph Roach	
Project Manager	February 11, 2018
Approved by	
Emmanuel Olotu, P.Eng.	
Technical Manager, Geotechnical	February 15, 2018