



**SGS MUSCOWPETUNG**  
**ABORIGINAL CONSTRUCTION MONITORING**  
**WEEKLY REPORT**  
**SPREAD 3**  
**AUGUST 28<sup>TH</sup> TO SEPTEMBER 02<sup>ND</sup>**

**SGS Canada Inc.** #1450 – 407 2<sup>nd</sup> Street SW (14<sup>th</sup> Floor) , Calgary Alberta T2P2Y3 t: (403) 278-9730 [www.sgs.com](http://www.sgs.com)

**ISO 9001: 2008 Registered OHSAS 18001:2007 Registered**



### Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	0			
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	0			

### Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	1	Pink skeleton weed		No
Aquatic Life	3			
Animal Observations or Burrows				
Bird Nests				
Trees (Red Willow)				
Wetlands				No
Watercourse Crossing	1	North Sask River		No

## Additional Observations and Summary of Activities or Concerns

This week's construction started on the east side of the river KP 338+000 working with an environmental specialist. The spread 3 team predominantly investigated towards the river to confirm and inspect some rare plants in the area and document with photos. The spread 3 team then confirmed how the plants and the surrounding area are being protected. The area is staked off and the plants are staked off as well so they know exactly where they are and where to not strip or do any construction. This is the view from the East side where they will be pulling the pipe through and underneath the river and on the other side is where the drill will be set up.

From the Environmental teams perspective there are currently no Issues that we are aware of.

## Photos of Sites Visited & Topics Discussed This Week



From kickoff KP 450+000 they started ditching and stringing pipe.



(Left) is a picture of equipment digging ditch.(Right) is a picture of Pipe beside the ditch waiting to be welded together and to be lowered into the ditch.

## Approvals

### Prepared by



---

Travis Favel  
Senior Construction Monitor

---

September 20, 2017

### Reviewed by



---

Joseph Roach  
Project Manager

---

September 20, 2017

### Approved by

---

Edison Reis  
Canada's IND Quality Manager

---

September 20, 2017