

SGS MUSCOWPETUNG

ABORIGINAL CONSTRUCTION MONITORING

WEEKLY REPORT

SPREAD # 3

JANUARY 8TH TO JANUARY 14TH, 2018

www. sgs.com



Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	0			
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	0			

Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	0			
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	0			
Trees (Red Willow)	0			
Wetlands	1	Cleaning up ramps and Geotech over wet lands	Ongoing	No
Watercourse Crossing	1	South Saskatchewan River Crossing. Horizontal directional drilling and testing the water turbidity.	South Saskatchewan Crossing ongoing.	Ongoing

ISO 9001: 2008 Registered OHSAS 18001:2007 Registered



Additional Observations and Summary of Activities or Concerns

The horizontal directional drilling at the South Saskatchewan River is continuing. Mears group had reached 1100 metres with the 48-inch reamer as of Saturday. They are close to reaming out currently.

Reclamations of wetlands is ongoing; there are only a few remaining in spread three. Some wetlands have been completed. Topsoil and grating back the soil is looking good and there are no concerns. Temporary access approaches have been removed and cleaned up. Crews have also been working on making water ways on the soil piles.

There was an installation of a valve on the mainline this week that was completed and there were no issues. They are currently working on excavating the location where the next valve will be installed on the mainline.

Golder Associates are still testing the turbidity of the water on the east side of the river and it remains consistent throughout the week.



Photos of Sites Visited & Topics Discussed This Week



Exit point of Horizontal Directional Drilling





Removing Geotech material from access approach






INFUSING BUOYANCY LINE INTO BORE SECTION





WATER SAMPLING





VALVE SITE





WETLAND RECLAMATION

Page 9 of 17





ENTRY POINT OF HORIZONTAL DIRECTIONAL DRILLING





THE CLEANING UP OF THE RIGHT OF WAY





RECLAMATION OF WETLANDS






INSTALLATION OF VALVE






RECLAMATION OF WETLANDS





VALVEINSTALLATION





ENTRY POINT OF HORIZONTAL DIRECTIONAL DRILLING



Approvals

Prepared by

/m/m	
— Gary Gopher	
Senior Construction Monitor	January 14, 2018
Reviewed by	
J Rock	
 Joseph Roach	
Project Manager	January 14, 2018
Approved by	
15/15 .	
Emmanuel Olotu, P.Eng.	
Technical Manager Geotechnical	January 16, 2018

SGS Canada Inc.

#1450 – 407 2^{nd} Street SW (14th Floor) , Calgary Alberta T2P2Y3 $\,$ t: (403) 278-9730

ISO 9001: 2008 Registered OHSAS 18001:2007 Registered