



**SGS MUSCOWPETUNG**

**ABORIGINAL CONSTRUCTION MONITORING**

**WEEKLY REPORT**

**SPREAD 6**

**MAR 11<sup>th</sup> TO MARCH 17<sup>th</sup>, 2019**

### Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)				
Rock Formations (rocks of significance, tipi rings, etc.)				
Artifacts				
Bones				
Potential Gravesites				

### Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants				
Aquatic Life				
Animal Observations or Burrows				
Bird Nests				
Trees (Red Willow)				
Wetlands	Many	772 + 700 SK 908 Class IV 772 + 200 SK 909 Class V 775 + 150 SK 911 Class IV 782 + 120 SK 935 Class IV 791 + 750 MB 012 Class IV	Ramps removed	No
Watercourse Crossing				

## Additional Observations and Summary of Activities or Concerns

This week our team continued to observe/monitor wetland ramps removal and spring mitigation. Wetlands on spread six that had ramps removed within various areas included. 772 + 700 SK 908, 772 +200 SK 909 775+ 150 SK 911, 782 +120 SK 935, 791+ 750 MB 012. Silt fencing, berms and catch basins were completed at all water crossings.

This part of the project was finishing up this week with spring mitigation and machine clean up our team travelled to various Heritage sites to observe the areas.

805 + 200 – 806 + 200 HER 147, 148,149,150,151,152, Wing walls were down due to deer crossing over the matted area protecting the rocks of interest. The area of interest with the no foot traffic signage was still in place. MB 1010 The Pipestone Creek – Silt fencing across the bridge is partly taken down. On the Creek observed the amber light with signage and willows sticks with ribbon attached and one pylon. Our team followed up the following day and the items on the creek were removed. Further observed the ice bridge cut for water flow through and an additional berm built on south side. Observed Heritage Resource 189 at 802 + 500 & Heritage Resource 147, 148 and 149 at 801 + 500 - 802 + 500 (no concerns) 787 + 500 SK WC 89 Observed the crew cleaning up the area on west side of the creek. 786 + 500 Heritage Resource 140 right of way clean up completed. Observed 788 + 700 Heritage Resource area of interest roped off with the nine Heritage markers. (no concerns). 776 + 900 – 779 + 500 Jackson Creek – observed the area (no concerns) – 778 + 900 labour monitoring the brush pile burning. 746 + 950 Observed the area for any debris left behind. Little pieces of geotextile and piles of brush were cleaned up the next day Heritage # 46 TLU area no further concerns. 747 + 920 Observed and assessed the area (no concern's) Heritage # 137 TLU SK WC 86.

Additional observations included 805 + 300 - MLBV#23A Backfilling was completed this week, sub base was hauled in and packed at valve location. Once backfilling was completed a fence was installed around the valve site. Access ramps were removed at various locations. Heavy equipment and the test heads were loaded and moved off site. Machine clean-up was completed through Spread six (6).

Construction on the reclamation will continue in late spring.

## Photos of Sites Visited & Topics Discussed This Week



772 + 700 SK 908 Class IV Ramp removed



775 + 150 SK 911 Class IV Ramp removed



772 +200 SK 909 Class V Ramp removed



805 + 300 MLBV #23A Backfilled and packing.



805 + 600 The Pipestone Creek MB 1010



## Prepared by

D. Masney

D. Masney  
Senior Construction Monitor

March 17th, 2019

## REVIEWED BY

J Roach

Joseph Roach  
Project Manager

March 19th, 2019

## APPROVED BY

Emmanuel Olotu

Emmanuel Olotu, P.Eng.  
Technical Manager, Geotechnical

March 19th, 2019





This document is issued by the Company under its General Conditions of Service available on request and accessible at [http://www.sgs.com/terms\\_and\\_conditions.htm](http://www.sgs.com/terms_and_conditions.htm). Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content of appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.