

**SWAN LAKE FIRST NATION – MATRIX SOLUTIONS  
INC. PARTNERSHIP**

**INDIGENOUS CONSTRUCTION MONITORING**

**WEEKLY REPORT**

**SPREAD 7**

**AUGUST 7<sup>TH</sup> TO AUGUST 11<sup>TH</sup>**

## **1. PURPOSE OF THIS REPORT**

The report is a weekly summary of the daily reports submitted by the Indigenous Construction Monitors that are working on spread seven. The social and cultural findings have been tabulated with locations and mitigation measures below. A summary of the construction activities has been summarized for the weeks of August 7<sup>th</sup> to August 11<sup>th</sup>, 2018.

### Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	N/A			
Rock Formations (rocks of significance, tipi rings, etc.)	N/A			
Artifacts	N/A			
Bones	N/A			
Potential Gravesites	N/A			

### Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	N/A			
Aquatic Life	N/A			
Animal Observations or Burrows	N/A			
Bird Nests	N/A			
Trees (Red Willow)	N/A			
Wetlands	N/A			
Watercourse Crossing	1	Excavation near Black Creek river bed.	Monitor	No

### **Additional Observations and Summary of Activities or Concerns**

Attended daily safety meetings at Banister Yard and tool box meetings on the ROW. Weekly activity included becoming familiar with the access points on the ROW and checking Rd 49 through to Rd 64.

August 7, 2018 safety included: be aware of your surroundings while driving and watch for slips, trips and falls. Weather forecast was sunny. Spent the day driving to access points to become familiar with the ROW and monitor activities on the ROW.

August 8, 2018 Safety included: watch for extreme heat and humidity. Ensure the Bio-security measures are being followed. Observed one hydro vac working at Rd 59 and stopped briefly to converse with the flag person. Work forecast is to be at Rd 59, Black Creek for environmental monitoring.

August 9, 2018 – Attended safety meeting at Enbridge Office. Safety included: Very dusty so slow down when meeting other vehicles. A car back fired and caused a grass fire due to heat and dry weather. Weather forecast, very dry. Followed bio-security measures. Attended Tool box meeting at Rd 59, Black River. Observed goal post being erected, unloading of Excavator and arrival of porta potties. Work forecast to return back to Rd 59, Black River location.

August 10, 2018- Safety features included to watch for traffic hazards, leadership communication and follow the rules. Ensure the bio-security measures are being followed. Arrived at Rd 59, Black River for Tool Box meeting. Excavator working on a river bed. Informed by the foreman they were unloading a D-8 Dozer. Work forecast to return to Rd 59, Black River to continue with enviro duties.


August 11, 2018 – Safety feature was fire and the vehicle that backfired and caused a grassfire, stay hydrated. Weather forecast, hot. Follow bio-security measures. Attended tool box meeting at Rd 59. Observed excavator and monitored work it was doing. Work forecast to return to Rd 59 to continue monitoring enviro duties.

## Photos of Sites Visited & Topics Discussed This Week




Access to ROW at road 59 Black Creek

## APPROVALS

  
\_\_\_\_\_  
Grant Manningway  
Indigenous Construction Monitor

\_\_\_\_\_  
August 16, 2018  
Date

  
\_\_\_\_\_  
Daniel Tober  
Senior Environmental Scientist

\_\_\_\_\_  
August 15, 2018  
Date