



SGS MUSCOWPETUNG

ABORIGINAL CONSTRUCTION MONITORING

WEEKLY REPORT

SPREAD 6

JUNE 03RD TO JUNE 09TH, 2019.

Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	0			
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	0			

Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	0			
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	0			
Trees (Red Willow)	0			
Wetlands	0			
Watercourse Crossing	0			

Additional Observations and Summary of Activities or Concerns

New week, new spread. I arrived in Spread 6 with Enbridge inspector, crew foreman and spray crew to try and get some vegetation spraying completed. Some days proved to be quite a chore. If the wind speed is too high, then it just blows the spray everywhere, so no work can be done. Another problem we run into is if it is raining or it has rained, the sprayed chemical can't compound itself to the vegetation if it is wet. To try and beat these problems, we start a lot earlier than usual as it is not very windy that early in the morning. Therefore, it makes for a much longer day; sometimes that's what needed to get the job done. The spray crew works very good together. The primary spots that are being sprayed are the sides of the topsoil piles and vegetation growing on the flats of the ROW, including any extended work areas or the 5-meter buffer zone on either side of the right of way.

The indication was that it was going to be busier in the week or early next week as kick-off is planned for either Friday or next Monday. Until then, we will continue to start early and try to get the spraying completed.

Looking forward to next week when it will be much busier on the ROW.

Photos of Sites Visited & Topics Discussed This Week



Mixing chemicals to spray @ KP 527+900.



Spray crew meeting up for morning tool box meeting. KP 527+900.



Crew spraying from mobile unit. KP 784+000.



Hand spraying along top soil pile @ KP 784+000.

Approvals

Prepared by

Chris Burke

Chris Burke
Senior Construction Monitor

June 09, 2019

Reviewed by

Tariq Ilyas

Tariq Ilyas
Project Manager

June 10, 2019

Approved by



Emmanuel Olotu, P.Eng.
Technical Manager, Geotechnical

June 10, 2019



This document is issued by the Company under its General Conditions of Service available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content of appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.