

# Improved Integrity Program

In October 2018, Enbridge experienced a natural gas pipeline rupture on its BC Pipeline System, approximately 13.5 kilometers north of Prince George.

Since the incident, we've implemented an improved approach to pipeline safety and have implemented a comprehensive pipeline integrity program.


This improved integrity program goes well beyond industry standard.

## Program highlights:



- Enhanced pipeline inspections
- Improved maintenance screening criteria
- Increased integrity digs

**This is the most aggressive inspection program ever undertaken on this pipeline system.**



**42+**  
inline pipeline inspections.

**144**


integrity inspection digs.



**31**  
comprehensive  
engineering assessments.

**100%**

The T-South natural gas pipeline system is now 100 per cent inspected by the latest generation inline inspection tool.



**2x**

This tool has double the number of sensors.

At Enbridge no incident is acceptable—ever. If an incident were to occur, we will implement changes to ensure the ongoing safety of our pipeline system and the public.