



SGS MUSCOWPETUNG

ABORIGINAL CONSTRUCTION MONITORING

WEEKLY REPORT

SPREAD # 3

AUGUST 13TH TO AUGUST 19TH, 2018

Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	0			
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	0			

Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	0			
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	0			
Trees (Red Willow)	0			
Wetlands	0			
Watercourse Crossing	0			

Additional Observations and Summary of Activities or Concerns

This week the indication digs are still ongoing which are the testing for ovalities, anomalies and jeeps. In the final step of testing of the pipe they had sent a smart pig through the line which identifies ovalities, anomalies, and jeeps. This pin points exactly where they are located and will be dug up to be checked and fixed. There are two remaining to be completed.

Currently they are doing weed control starting from kick off and they were at road 14 of 75 as of Saturday. Fencing is still currently ongoing and they are on road 63 there are only a few more fences to build and they will be moving onto spread four.

Valves number 10 and 13 were completed along with backfilling. Valve 11 is currently being worked on and 12 is still currently awaiting backfilling.

Photos of Sites Visited & Topics Discussed This Week



Excavating ovality SSKP 399+617



Using crushed rocks as base MLBV #11



Washing equipment before move to next municipality.



Ovality dig. Road 67





Fine cleaning equipment



Compacting at MLBV #10



Fencing crew Road 57



MLBV #13





Weed control in ditches





Compacting MLBV #10



Compacting MLBV #10

Approvals

Prepared by



Gary Gopher
Senior Construction Monitor

August 18, 2018

Reviewed by



Joseph Roach
Project Manager

August 22, 2018

Approved by



Emmanuel Olotu, P.Eng.
Technical Manager, Geotechnical

August 22, 2018



This document is issued by the Company under its General Conditions of Service available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content of appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.