



SGS MUSCOWPETUNG

ABORIGINAL CONSTRUCTION MONITORING

WEEKLY REPORT

SPREAD # 3

SEPTEMBER 3RD TO SEPTEMBER 9TH, 2018

Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	0			
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	0			

Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	0			
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	0			
Trees (Red Willow)	0			
Wetlands	0			
Watercourse Crossing	0			


Additional Observations and Summary of Activities or Concerns

No activities on spread three this week because work is completed. The exception is the native pasture and native areas which they will be coming back to complete.

This week we spent our time in spread four. They are currently doing machine clean up and spreading of top soil and they are working their way back towards spread three. The process of final clean is that they decompact the sub soil with discers and graters and then they pull the second soils in and grade it evenly across the right of way. They rock pick it and disc it again then they pull in the top soil. This process is repeated with the top soil as previously mentioned. They are also building fences where they are needed. They are also doing straw crimping in spread four as a soil erosion prevention method.

At High Hill Creek, they are building diversion berms on the steep side of the right of way. This process will prevent the side of the hill sliding down.

Also, at the Qu'Appelle valley they are pushing back and grating the sub soil as close to what it was before. This is an ongoing process that will continue throughout the week. There is more work going on further down spread four but we did not venture that far down the spread. We will be working in spread four again this week.



Road 95,kp 458+526. Crew was; straw crimping,disking buffer zone for weeds, and rock picking.



Road 114, kp 499+300, High Hill Creek Native
Prairie zone.



Jeeping the pipe road 76



Assisting hydrovac truck into place road 114





Pulling topsoil over right of way kp 423+300



Pounding posts road 92



Spreading topsoil road 78



Nailing wire road 92



Ovality dig road 76



Approvals

Prepared by



Gary Gopher
Senior Construction Monitor

September 9, 2018

Reviewed by



Joseph Roach
Project Manager

September 11, 2018

Approved by



Emmanuel Olotu, P.Eng.
Technical Manager, Geotechnical

September 11, 2018

This document is issued by the Company under its General Conditions of Service available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alternation, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.