



**SGS MUSCOWPETUNG**

**ABORIGINAL CONSTRUCTION MONITORING**

**WEEKLY REPORT**

**SPREAD 4**

**AUGUST 5<sup>TH</sup> TO AUGUST 12<sup>TH</sup>, 2018**

## Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	0			
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	0			

## Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	0			
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	1	Sweeping ROW for bird nests		No
Trees (Red Willow)	0			
Wetlands	2	Weed trimming and mowing		No
Watercourse Crossing	1			No

### Additional Observations and Summary of Activities or Concerns

This week in Spread. 4 has been a scorcher. Environment Canada had issued extreme heat warning throughout the week. All crew have taken precautionary measures in regard to working in these temperatures. Staying hydrated, watching out for one another and taking micro breaks when needed was this week's main safety point. The Final clean up equipment crews have been working at a fast pace, getting a lot done throughout the days. Rocking picking had been on going, the crew had been walking through areas and getting all larger rocks picked up and disposed. At the beginning of this week the NCRS crews had not been on site due to shortage of work upon review the crews were called back to come cut weeds that had been left behind. The weed trimmers mainly focused on farmer and cattle access ways as well as areas around signs.

In a final note this week has been busy having all crews working at highly fast paces. This following week shall get busier as our monitors need to be monitoring in highly sensitive areas.

## Photos of Sites Visited & Topics Discussed This Week



Rock pickers going hands on.



Welders cutting water pipe and putting back onto trailer.



Weed trimmers cutting seconds pile.





Dozers levelling out topsoil.

## Approvals

### Prepared by

Leland Bull

Leland Bull  
Junior Construction Monitor

August 12th, 2018

August 12th, 2018


### Reviewed by



Joseph Roach  
Project Manager

August 15th, 2018

### Approved by



Edison Reis, P. Eng  
Industrial Quality Manager, Canada

August 15th, 2018



This document is issued by the Company under its General Conditions of Service available on request and accessible at [http://www.sgs.com/terms\\_and\\_conditions.htm](http://www.sgs.com/terms_and_conditions.htm). Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alternation, forgery or falsification of the content of appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.