



SGS MUSCOWPETUNG

ABORIGINAL CONSTRUCTION MONITORING

WEEKLY REPORT

SPREAD 4

AUGUST 13TH TO AUGUST 19TH, 2018

Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	1	High Pound Hill	Completion of work	no
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	2	High Pound Hill & Qu'appelle valley	Complete & On going	no

Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	0			
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	0			
Trees (Red Willow)	0			
Wetlands	2	Weed trimming and mowing		No
Watercourse Crossing	1	Qu' appelle creek		No

Additional Observations and Summary of Activities or Concerns

This week in spread 4 has been a busy one. Each crew has been working at an exceptional pace considering the mild weather. The final clean up crew is cruising along each day. At the beginning of this week the crews have been slowly getting prepared for the Native prairie zone at the High Pound Hill area. Equipment have been going through the fine clean station before even stepping foot in the zone, this measure prevents any spreading of seeds in the highly sensitive area. The trimmers have come back into the spread and have been trimming in areas that have been missed or areas that the weed spraying didn't completely work. It has also been there final week here as they will be straw crimping in the week to come. Mechanical clean up crew have been decompacting. (Breaking of large clumps on ROW) and also have been moving the topsoil piles for the dozers the completely move over topsoil for finished product.

In the middle of this week the Aboriginal Monitors met up with the Pasqua representatives. The crews have now reached the High Pound Hill area and have done an excellent job in completion of putting soils back together. Awesome to hear that the reps were happy about this area being done correctly.

Lastly this week has been well productive. The Following week we can expect some more production done. This coming week is to have mild temperatures in which will help the production and process of work.

Photos of Sites Visited & Topics Discussed This Week



Installation of Cathodic protection at Stoney Beach compound.



High Hill creek weed trimming.



Removal of water diversion berms at Qu'appelle valley.



Last dozer in High Pound hill moving a rare plant pile and levelling.

Approvals

Prepared by

Leland Bull

Leland Bull
Junior Construction Monitor

August 19th, 2018

August 19th, 2018

Reviewed by



Joseph Roach
Project Manager

August 22, 2018

Approved by



Emmanuel Olotu, P.Eng.
Technical Manager, Geotechnical

August 22, 2018

This document is issued by the Company under its General Conditions of Service available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content of appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.