



SGS MUSCOWPETUNG

ABORIGINAL CONSTRUCTION MONITORING

WEEKLY REPORT

SPREAD 4

SEPTEMBER 3RD TO SEPTEMBER 9TH, 2018

Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	2	At Qu'Appelle		
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	0			

Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	0			
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	0			
Trees (Red Willow)	0			
Wetlands	4	crimping		No
Watercourse Crossing	1			No

Additional Observations and Summary of Activities or Concerns

This week has been very excellent regarding the progress of work. After considerations to the long weekend the crew came back refreshed and motivated. The crews have been working at an excellent pace and getting things done. The aboriginal monitors of spread 4 have been giving the monitors from spread 3 a tour. The monitors have been in our spread due to no activity this week in spread 3. The monitors have noted that the progression of the project is in full swing. The final clean up crew has been flying in regard to getting work done. The activity in the Qu'Appelle Valley has been quite busy due to the crew spreading topsoil in the Valley. The Qu' Appelle Valley is a highly sensitive area regarding the Pasqua representatives. They were quite happy with the finishing results. The straw crimping is coming along excellently, they get a lot done during the day. The on-going work of Ovality digs (exposing of pipe and doing measurement tests all due to the smart pigs detecting imperfections)

This week has been very busy, the crews have been taken advantage of the weather which has been mild in the mornings then fair temperatures in the day time. This week has been busy due to the previous long weekend. It has been a very good week out in spread 4. The aboriginal monitors are looking forward to the up coming week ahead.

Photos of Sites Visited & Topics Discussed This Week



Ovality dig up crew taking measurements.



Panels (diversion berm) have been installed along the High Hill creek to fix the slopping problem.



Panoramic view at High Hill Creek during construction.



Qu'Appelle Valley Slope being put back, crew moving subsoil.

Approvals

Prepared by

Leland Bull

Leland Bull
Junior Construction Monitor

September 09, 2018

September 9, 2018

Reviewed by



Joseph Roach
Project Manager

September 11, 2018

Approved by



Emmanuel Olotu, P.Eng.
Technical Manager, Geotechnical

September 11, 2018

This document is issued by the Company under its General Conditions of Service available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.