

SGS MUSCOWPETUNG

ABORIGINAL CONSTRUCTION MONITORING

WEEKLY REPORT

SPREAD 3

AUGUST 21ST TO AUGUST 27TH

SGS Canada Inc. #1450 – 407 2nd Street SW (14th Floor) , Calgary Alberta T2P2Y3 **t:** (403) 278-9730 www. sgs.com

ISO 9001: 2008 Registered OHSAS 18001:2007 Registered



Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	0			
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	0			

Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants				
Aquatic Life	3			
Animal Observations or Burrows				
Bird Nests				
Trees (Red Willow)				
Wetlands	5	100m wetland		No
Watercourse Crossing	4	Canal in ROW		No

SGS Canada Inc. #1450 – 407 2nd Street SW (14th Floor), Calgary Alberta T2P2Y3 t: (403) 278-9730 www. sgs.com

ISO 9001: 2008 Registered OHSAS 18001:2007 Registered



Additional Observations and Summary of Activities or Concerns

This week construction started on the west side of the river; The top soil was stripped to make the Right of way to where the bore will be drilled. The river was a busy work area as a result access is limited for safety concerns, a detail inspection will commence once it is safe to so. Wild life habitat areas were observed to see how certain species of bird are being protected, frogs and other wild life were also observed. Fences have been put up around certain areas of Habitat that are vulnerable on the right of way, and other areas are flagged off so they are easily identifiable.

From the Environmental teams perspective there are currently no Issues that we are aware of.

Photos Of Sites Visited & Topics Discussed This Week



(Dark brown is stripped soil, light brown is riparian area and green is where it is fenced off for frog habitat.)





Bore crew to dig underneath roads. Ditch soil, top soil, transitional soil are all separated to ensure there is no cross contamination.

SGS Canada Inc. #1450 – 407 2nd Street SW (14th Floor) , Calgary Alberta T2P2Y3 t: (403) 278-9730 www. sgs.com

ISO 9001: 2008 Registered OHSAS 18001:2007 Registered





Pipe down the Right of way.



Approvals

Prepared by

Canada's IND Quality Manager

20/	
Travis Favel	
Senior Construction Monitor	September 20, 2017
Reviewed by	
J Rock	
Joseph Roach	
Project Manager	September 20, 2017
Approved by	
Edison Reis	

SGS Canada Inc. #1450 – 407 2nd Street SW (14th Floor) , Calgary Alberta T2P2Y3 **t:** (403) 278-9730 www. sgs.com

ISO 9001: 2008 Registered OHSAS 18001:2007 Registered

September 20, 2017