



SGS MUSCOWPETUNG

ABORIGINAL CONSTRUCTION MONITORING

WEEKLY REPORT

SPREAD 4

AUGUST 14TH TO AUGUST 20TH



Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	0			
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	0			

Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	0			
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	0			
Trees (Red Willow)	0			
Wetlands	0			
Watercourse Crossing	0			

Additional Observations and Summary of Activities or Concerns

This week's construction was our first week of field work in Outlook. We did Our Bio-security training prior to starting in the field. We were Shadowing an environmental specialist to learn about the mitigations measures they need to have on certain areas of construction. Also were assigned to shadow a CAEPLA Monitor to learn some of what he watches for.

Photos of Sites Visited & Topics Discussed This Week

No photo's to show this week.

Approvals

Prepared by

Chris Burke

Chris Burke
Senior Construction Monitor

September 23, 2017

Reviewed by

J Roach

Joseph Roach
Project Manager

September 24, 2017

Approved by

Edison Reis

Edison Reis
Canada's IND Quality Manager

September 24, 2017

