

### **SGS MUSCOWPETUNG**

# **ABORIGINAL CONSTRUCTION MONITORING**

**WEEKLY REPORT** 

SPREAD 4

NOVEMBER 26<sup>TH</sup> TO DECEMBER 2<sup>ND</sup>, 2018

www. sgs.com



#### **Social and Cultural Features**

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	7	Native prairie zone.		No
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	0			

#### **Environmental Features**

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	0			
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	0			
Trees (Red Willow)	0			
Wetlands	0			
Watercourse Crossing	0			



#### **Additional Observations and Summary of Activities or Concerns**

The past week was spent exclusively at the Bethune pipe yard on spread 4 working on the access road to valve 14. When work was first started, it was assumed that the entire road would be finished completely by December. But it was decided that they could not get the right compaction down with the weather being so cold. So, it was decided to just strip the top soil to the end of the fence line and clean up the soil piles neatly until next year when it is warm out. A grader was used to make the existing road as level and smooth as it could be for work to commence next year. The crew worked everyday and were able to finish last Friday.

We will be back next week, for only one or two days to complete grading the access road for next year.




## **Photos of Sites Visited & Topics Discussed This Week**



STRIPPING TOP SOIL FROM ACCESS ROAD.

www. sgs.com





LEVELLING ACCESS ROAD WITH GRADER.



### **Approvals**

### **Prepared by**

Christopher Burke	<u>December 4, 2018</u>
Christopher Burke	
Senior Construction Monitor	December 4, 2018
Reviewed by	
J Rock	
Joseph Roach	 December 5, 2018
Project Manager	
Approved by	
<del>1</del> .	
Emmanuel Olotu, P.Eng.	December 5, 2018
Technical Manager, Geotechnical	



This document is issued by the Company under its General Conditions of Service available on request and accessible at <a href="http://www.sgs.com/terms\_and\_conditions.htm">http://www.sgs.com/terms\_and\_conditions.htm</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alternation, forgery or falsification of the content of appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.