



SGS MUSCOWPETUNG

ABORIGINAL CONSTRUCTION MONITORING

WEEKLY REPORT

SPREAD # 4

OCTOBER 22ND TO OCTOBER 28TH, 2018

Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	1	High Pound Hill	Completion of work	No
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	2	High Pound Hill & Qu'appelle valley	Complete & On going	No

Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	0			
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	0			
Trees (Red Willow)	0			
Wetlands	0			
Watercourse Crossing				

Additional Observations and Summary of Activities or Concerns

At the beginning of this week, the aboriginal monitors have mainly turned there focused to the NCRS Straw crimping crew. With having only this crew in our spread for this week they have been quite busy taking advantage of the warmer temperatures. The crew continue to spread straw throughout the Right of Way, followed by a tractor with harrowing attachment which starts to crimp the straw. To finish off the sections the NCRS labour workers begin walking down the ROW in search of any left-over twine, garbage or unnecessary rocks that are left behind. The fencers came back to our spread at the end of this week to install fence at a farmer's request. With the production of work still in full force the Crew keeps working at a very fast pace to get the work done until the weather in this good weather. The work week has come and gone the Monitors are very happy with the production thus far.

Photos of Sites Visited & Topics Discussed This Week



Spreading the straw throughout the ROW.



Seeding on the east slope of the High Hill Creek



Small cleaning station installed as the NCRS straw crimping crew enter an Organic Zone.



NCRS labour workers walking down ROW picking up garbage.

Approvals

Prepared by

Leland Bull

Leland Bull
Senior Construction Monitor

October 28th, 2018

October 28th, 2018

Reviewed by



Joseph Roach
Project Manager

October 30, 2018

Approved by



Emmanuel Olotu, P.Eng.
Technical Manager, Geotechnical

October 30, 2018

This document is issued by the Company under its General Conditions of Service available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alternation, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.