

SGS MUSCOWPETUNG

ABORIGINAL CONSTRUCTION MONITORING

WEEKLY REPORT

SPREAD 5

JULY 23RD TO JULY 29TH, 2018



Social and Cultural Features

| Field Observation | # of occurrences | Description and Mitigation Measures | Mitigation Status | Further Action Required (Yes/No) |
|--|------------------|--|-------------------|--|
| Traditional Use Area (hunting, fishing, gathering, trapping) | 1 | Chapleau Lake KP624+000 | Monitoring Area | Υ |
| Rock Formations (rocks of significance, tipi rings, etc.) | 1 | 5 tipi rings 1 cairn east of WC-68 | Monitoring area | Y |
| Artifacts | 0 | | | |
| Bones | 0 | | | |
| Potential Gravesites | 0 | | | |

Environmental Features

| Field Observation | # of occurrences | Description and Mitigation Measures | Mitigation Status | Further Action Required (Yes/No) |
|--------------------------------|------------------|--|----------------------|--|
| Medicinal or Cultural Plants | 1 | Sage | Went through area | Y |
| Aquatic Life | 0 | | | |
| Animal Observations or Burrows | 0 | | | |
| Bird Nests | 1 | SSKP624+860 | Environment notified | Υ |
| Trees (Red Willow) | 0 | | | |
| Wetlands | 0 | | | |
| Watercourse Crossing | 1 | Wascana Creek SK WC-1002 | Monitoring area | Υ |

ISO 9001: 2008 Registered OHSAS 18001:2007 Registered



Additional Observations and Summary of Activities or Concerns

This week, spread five is gearing up for construction making sure everything in in order for August first, when construction is set to begin. All Aboriginal Monitors went out to Chapleau Lake SSKP524+860 and joined Archaeologist Steve Kasston on the east side of the lake. He had Meridian surveyors mapping each rock by GPS individually near the Horizontal Directional Drilling Site on the east side of Chapleau Lake. Outcome from GPS mapping there were circle formations, arcs and a cairn identified and were recorded, from that these areas will be fenced off before construction begins, markers have been put in place in those areas.

During a tour with Dean Bellegarde, Enbridge Construction Specialist took him out to Chapleau Lake showed him the Archaeological sites that were mapped and recorded. During that visit a bird's nest was found on Right of Way by a Jr Construction Monitor and it was reported to Denny Hayes of Enbridge and Larry Lynn of Banister, a stake was put near the nest for the bird sweepers and environmentalists.

Bird activity tends to slow down around noon, which is why the bird sweepers usually start at dawn to get more areas swept on the right of way before the other crews start their work day.

A tour for the Carry the Kettle First Nation Knowledge holders was on Saturday, we had three planned stops on spread five throughout the day. First stop was at SK WC-1002 Wascana Creek, before going onto Right of Way we bio sprayed everyone's boots, equipment, tires and headed to the creek to look at an area. The group headed to the next site SSKP572+000 where there was an identified archaeological site found on a previous project they plant knowledge holders spoke a bit more on uses of the medicine picked in the areas. The next stop was at SSKP577+000 this area they picked sage and gum weed and a few others, pictured below.



Photos of Sites Visited & Topics Discussed This Week



Weeds and plants picked from SSKP577+000, During the CTK tour was asked to identify plants in picture by one of the CTK plant knowledge holders.





Birds nest found on SSKP526+000 ROW by Aboriginal Construction Monitor on routine visit out to site, Denny Hayes of Enbridge and Larry Lynn of Banister were notified and a stake was put near the nest for the bird sweepers and environmental group to find, bird buffer was put in place the following day.



Approvals

Prepared by

| <u>Jenniter Wolte</u> | · |
|------------------------------------|----------------|
| Jennifer Wolfe | |
| Senior Construction Monitor | July 29, 2018 |
| Reviewed by | |
| J Rock | |
| Joseph Roach | |
| Project Manager | August 1, 2018 |
| Approved by | |
| | |
| Edison Reis, P. Eng | |
| Industrial Quality Manager, Canada | August 1, 2018 |