

SGS MUSCOWPETUNG

ABORIGINAL CONSTRUCTION MONITORING

WEEKLY REPORT

SPREAD 5

JULY 16TH TO JULY 22ST, 2018

SGS Canada Inc. #1450 – 407 2nd Street SW (14th Floor), Calgary Alberta T2P2Y3 t: (403) 278-9730



Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	1	Chapleau Lake KP624+000	Monitoring Area	Y
Rock Formations (rocks of significance, tipi rings, etc.)	1	5 tipi rings 1 caron east of WC-68	Monitoring area	Y
Artifacts	0			
Bones	0			
Potential Gravesites	0			

Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	1	Rare plant (Northern blue-eyed grass)	Monitoring area	Y
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	0			
Trees (Red Willow)	0			
Wetlands	0			
Watercourse Crossing	1	Chapleau Lake SKWC-68	Monitoring area	Y

#1450 - 407 2nd Street SW (14th Floor) , Calgary Alberta T2P2Y3 t: (403) 278-9730



Additional Observations and Summary of Activities or Concerns

I started in my new role as Sr Monitor on Thursday July 19, 2018 on spread Five, first day I met with the new team from spread five and six, all attended Banister Orientation in white city. Once orientation was done spoke on what our duties would be out in the field having experience from spreads three and four (providing each with a cheat sheet). Ensuring the trucks were properly equipped (spray bottles, shovels, pails) and acquired all PPE (all had no gloves) before going out to ROW or shoofly access roads. Also, did a quick overview of biosecurity demonstration with the truck, washed, took pictures and use of spray bottle. Went over reports, deadlines and any other questions they could have had. Handed out spread five alignment sheets spread six would be handed out next day. On Friday, we had official bio security training all attended, and I requested CH2Mobile App for all monitors via email, we then headed out for the day boots on the ground finding Kick off and made our way to SF56 KP629+000.

July 21, Travelled to KP 624+000 Chapleau Archaeological site, signed in on job site, bleached boots before entering ROW in one truck, met Enbridge Archaeologist Steve Kasston and he went over the significance of the site, the Horizontal Directional Drilling(HDD) process and he was utilizing the Surveyors by marking each rock by GPS to use for future reference and see how the land moves. In the same location on the north of ROW an integrity dig site was cordoned off by rope and signs checking on the pipeline to eventually bring in a pig head to hydrotest the line. Sweepers were also on ROW going around looking for unmarked underground lines or anything not found already.

The week of July 23rd to July 28th the aboriginal construction monitors from both spread five and six are invited to attend a ceremony on Tuesday in CTK, and traditional walks will be held on Wednesday to Friday with a pre-construction tour for neighbouring first nations sometime during the week. (not sure on exact dates of activities)

www.sas.com



It is with also great sadness to have found out one of the Indigenous leaders Lindsay Cyr from Pasqua First Nation had passed away, he spear headed the Buffalo Rock move on Spread 4 and set up the ceremonial gatherings on the project. He will be missed!



Spread 4, Buffalo Rock Move November 2, 2017

Buffalo Rock, Outside Regina July 2018





SGS Canada Inc.

#1450 – 407 2nd Street SW (14th Floor) , Calgary Alberta T2P2Y3 t: (403) 278-9730

www.sgs.com



Photos of Sites Visited & Topics Discussed This Week



Chapleau Archaeological site HDD site



Surveyors sweeping for underground lines

SGS Canada Inc.

#1450 - 407 2nd Street SW (14th Floor) , Calgary Alberta T2P2Y3 t: (403) 278-9730

www.sgs.com



Approvals

Prepared by

Jennífer Wolfe

Jennifer Wolfe Senior Construction Monitor

July 23, 2018

Reviewed by

Joseph Roach Project Manager

July 25, 2018

Approved by

Emmanuel Olotu, P.Eng. Technical Manager, Geotechnical

July 25, 2018

SGS Canada Inc.

www.sgs.com

#1450 – 407 2nd Street SW (14th Floor) , Calgary Alberta T2P2Y3 t: (403) 278-9730 ISO 9001: 2008 Registered OHSAS 18001:2007 Registered



This document is issued by the Company under its General Conditions of Service available on request and accessible at <u>http://www.sgs.com/terms_and_conditions.htm</u>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alternation, forgery or falsification of the content of appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

#1450 – 407 2nd Street SW (14th Floor) , Calgary Alberta T2P2Y3 t: (403) 278-9730