

SGS MUSCOWPETUNG

ABORIGINAL CONSTRUCTION MONITORING

WEEKLY REPORT

SPREAD 6

MAY 27^{TH} TO JUNE 2^{ND} , 2019



Social and Cultural Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Traditional Use Area (hunting, fishing, gathering, trapping)	0			
Rock Formations (rocks of significance, tipi rings, etc.)	0			
Artifacts	0			
Bones	0			
Potential Gravesites	0			

Environmental Features

Field Observation	# of occurrences	Description and Mitigation Measures	Mitigation Status	Further Action Required (Yes/No)
Medicinal or Cultural Plants	0			
Aquatic Life	0			
Animal Observations or Burrows	0			
Bird Nests	0			
Trees (Red Willow)	0			
Wetlands	0			
Watercourse Crossing	0			

ISO 9001: 2008 Registered OHSAS 18001:2007 Registered



Additional Observations and Summary of Activities or Concerns

At the beginning of the week, clean up continued on spread 6, starting off at a pipe yard area by picking up debris and raking up areas which had smaller debris parts such as broken pieces of skids, plastic, damaged rope and other material which was piled up to be later discarded. Moving back onto right of way clean up picking up broken signs, damaged snow fence, skids, repairing wingwalls at roadsides and picking up about one million t-posts. This continued for the rest of the week until we completed spread 6 clean up tour, it was tough with the blast of heat that hit us in mid week, but the crew continued working and the clean up tour was completed by Thursday.



Photos of Sites Visited & Topics Discussed This Week



Pipe yard - raking up smaller pieces in piles



Debris pile - skids





Repairing snow fence around wet land area



Roping off an area where the soil settled over mainline





Removing damaged snow fence



Debris pile



Approvals Prepared by Jennifer Wolfe Jennifer Wolfe Senior Construction Monitor June 2nd, 2019 **Reviewed by** Tariq Ilyas Tariq Ilyas Project Manager June 03, 2019 **Approved by**



Emmanuel Olotu, P.Eng.

Technical Manager, Geotechnical

June 03, 2019



This document is issued by the Company under its General Conditions of Service available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alternation, forgery or falsification of the content of appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.